

Kashiyama	Lucas	FSB	Lockheed	OEM	Application
K148	GS8111	FSB134	LS1254		NISSAN
K149	GS8096	FSB140	LS1252		NISSAN
K160	GS8156	FSB179	LS1289		NISSAN
K164	GS8157	FSB309		D4060-01B25	NISSAN
K170	GS8308	FSB258	LS1405		NISSAN
K232				04497-14031	TOYOTA
K252					TOYOTA
K282	GS8184	FSB284	LS1409		TOYOTA
K282A					TOYOTA
K259					TOYOTA
K240					TOYOTA
K256	GS8143	FSB254	LS1368	04494-26070	TOYOTA
K280	GS8502 / GS8601	FSB213	LS1711		TOYOTA
K179				440601Y427	NISSAN
K288	GS8224 / GS8181	FSB241	LS1356/LS1601		TOYOTA
K287	GS8182	FSB185	LS1294		TOYOTA
K2305	GS8501	FSB411	LS1406		TOYOTA
K2317	GS8593	FSB324	LS1654		TOYOTA
K2330	GS8693	FSB563	LS1744		TOYOTA
K664	GS8185	FSB249	LS1344		MITSUBISHI
K167	GS8246	FSB222	LS1410		NISSAN
K196				44070-04A00	NISSAN
K646	GS8518		LS1345		MITSUBISHI
K626	GS8070	FSB145			DODGE-PLYMOUTH
K516	GS8215	FSB231	LS1417		HONDA
K524	GS8559	FSB318	LS1641		HONDA
K369	GS8519	FSB264	LS1437		MAZDA-KIA
K210					TOYOTA-DAIHATSU
K402				5-47110060	ISUZU
K238				04494-28010- 000	DAIHATSU
K602				MB326388	MITSUBISHI
K627				MB060235Y	MITSUBISHI
K324	GS8086		LS1325		MAZDA
K653					MITSUBISHI
K344	GS8197	FSB189	LS1325		MAZDA
K016					HONDA
K255					TOYOTA
K174	GS8512	FSB282	LS1553		NISSAN
K260	GS8170	FSB184	LS1335		TOYOTA
K151					NISSAN
K162	GS8259	FSB251	LS1366		NISSAN
					BUICK
K290	GS8243	FSB224	LS1333		TOYOTA
K2321	GS8554		LS1638		TOYOTA
K156					NISSAN
K285	GS8181	FSB208			TOYOTA
K637					MITSUBISHI
K462					ISUZU
K902				52210-58040	SUZUKI
K904				52210-79020	SUZUKI
K6715	GS8667			MR496334	MITSUBISHI
					FORD
K221					TOYOTA

K357					MAZDA
K11155	GS8568	FSB310/FSB605	LS1609		HYUNDAI
					HYUNDAI
					FORD
					FORD
					FORD
K921	GS8548	FSB340			SUZUKI
K372	GS8520	FSB276	LS1546		MAZDA
K914	GS8597	FSB413	LS1710		SUZUKI
K336					MAZDA
K337					MAZDA
K348					MAZDA
K349	GS8523	FSB288	LS1476		MAZDA
K378	GS8550		LS1706		MAZDA
K008					DAIHATSU
K009	GS8139	FSB160	LS1284?		DAIHATSU
K284	GS8500	FSB40	LS1353		TOYOTA
K275					TOYOTA
K910	GS8195	FSB190	LS1467		SUZUKI
K146	GS8183	FSB250	LS1367		NISSAN
K152					NISSAN
K265					TOYOTA
K266					TOYOTA
K356	GS8286	FSB238	LS1324		MAZDA
K11003	GS8025	FSB11	LS1098		HONDA
K520	GS8245	FSB402	LS1341		MAZDA
K329	GS8125		LS1278		MAZDA
K518	GS6210	FSB204			HONDA
K185	GS8556	FSB412	LS1650		NISSAN
K6701	GS8666	FSB404	LS1643		MITSUBISHI
K452	GS8551	FSB471			ISUZU
K385	GS8582	FSB540	LS1679		MAZDA
K448					GEO
K6712	GS8553	FSB403	LS1649		MITSUBISHI
			LS1807		HYUNDAI
K105					NISSAN
		FSB651			LAND ROVER
	GS8633	FSB556			LAND ROVER
K2311	GS8291		LS1600		TOYOTA
K441					ISUZU
K618A					SUZUKI
	GS8531	FSB337	LS1681		CITROEN
K11024					MERCURY
K11097					CITROEN
	GS8148 / GS8598	FSB407/FSB391			IVECO
	GS6220		LS1261		IVECO
K11062					FORD
K11064					FORD
K674	GS8225	FSB246	LS1343/LS1779		MITSUBISHI
K670					MITSUBISHI
K1213					
K11019					
K933					SUZUKI

	GS8692 / GS8675	FSB516			KIA
K6718	GS8691	FSB617			MITSUBISHI
	GS8543	FSB335	LS1622	96430417	DAEWOO
K2350	GS7338				TOYOTA
K958	GS8670	FSB578	LS1882		SUZUKI
K394	GS8661	FSB573			MAZDA
K443					ISUZU
	GS8223	FSB227	LS1381		OPEL
K2329					TOYOTA
	GS8218	FSB63	LS1372		MERCEDES
	GS8208	FSB196	LS1371		MERCEDES
K11102					
K11078					
K633	GS8178	FSB162	LS1328		MITSUBISHI
K11083					
K11115	GS8644		LS1773		CHRYSLER
K343	GS8255	FSB156	LS1456		MAZDA
K669					MITSUBISHI
K358	GS8288	FSB239	LS1501		MAZDA
K032	GS8549	FSB341	LS1685		SUZUKI
K2345					TOYOTA
K687					MITSUBISHI
K955	GS8671				SUZUKI
K947/K965	GS8641	FSB580	LS1845		SUZUKI
	GS8643	FSB568	LS1814		KIA
K918					SUZUKI
K919					MAZDA
K432					
K350					MAZDA
K320					MAZDA
K028					DAIHATSU
K2363					TOYOTA
K239					TOYOTA
K249					TOYOTA
K347	GS8205	FSB210			MAZDA
K937					SUZUKI
K6729					MITSUBISHI
K11098					
K917	GS8278		LS1339		SUZUKI
K326					MAZDA
K159					NISSAN

K158	GS8159		LS1334		NISSAN
	GS8636	FSB565			FORD
	GS8536	FSB422	LS1684		
K2342	GS8673	FSB582			TOYOTA
	GS8542	FSB334	LS1621		
K019					DAIHATSU
K024	GS8699		LS1812		DAIHATSU
	GS8524 / gs6237	FSB526/FSB173	LS1690		
K202	GS8304		LS1569		TOYOTA
K307	GS8042	FSB53	LS1275		MAZDA
K11148	GS8552	FSB269	LS1514		
K11158	GS8569 / GS8678	FSB319			
K2358					TOYOTA
K373	GS8290	FSB315	LS1516		MAZDA
	GS8530	FSB428	LS1656		VOLKSWAGEN
	GS6181	FSB361/FSB533	LS1179		FORD
	GS8173	FSB174	LS1301		
K293					TOYOTA
K2301					TOYOTA
K2312	GS8649 / gs8449	FSB342	LS1745		TOYOTA
K434					ISUZU
K1230	GS8655	FSB577	LS1802		RENAULT
	GS8442	FSB604	LS1916		FIAT
	GS8631 / GS8240	FSB401/308			ALFA ROMEO
	GS8436	FSB594			FORD
	GS8669	FSB584			RENAULT
	GS8166	FSB191	LS1276		VOLKSWAGEN
		FSB408	LS1277R		
K029	GS8648 / GS8283	FSB416			DAIHATSU
K034	GS8281	FSB314	LS1509		DAIHATSU
	GS8594	FSB546	LS1704		BMW
K171	GS8513	FSB317	LS1504		NISSAN
K175	GS8515	FSB251	LS1366		NISSAN
K257					TOYOTA
K267					TOYOTA
K268					TOYOTA
K289					TOYOTA
K294					TOYOTA
K295					TOYOTA
K296					TOYOTA
K425					ISUZU
K429					ISUZU
K431	GS6204	FSB211	LS1310		ISUZU
	GS8217	FSB272	LS1573		BMW

K442				ISUZU
K697				MITSUBISHI
K698				MITSUBISHI
K728	GS8302	FSB252	LS1352	SUBARU
K943				MAZDA
	GS8544	FSB273		AUDI
	GS8646 / gs8645	FSB566		
K504	GS8071	FSB52	LS1213	HONDA
K510	GS8085	FSB163	LS1240	HONDA
K514	GS8194	FSB161	LS1316	HONDA
	GS6212	FSB198	LS1292	DAEWOO
K451				OPEL
	GS8092	FSB150		
	GS8455	FSB642		RENAULT
K636	GS8249 / GS8221	FSB228	LS1327/LS1471	MITSUBISHI
K932				MAZDA
		FSB606		
K399/K382				MAZDA
	GS8492	FSB650		TOYOTA
	GS8688	FSB536		MERCEDES
	GS8219	FSB92	LS1370	BMW
K1221	GS8529	FSB308	LS1620	NISSAN
K103				NISSAN
	GS8659	FSB586		HYUNDAI
	GS8595	FSB539		MERCEDES
	GS8639	FSB549		SKODA
K600				MITSUBISHI
	GS8544	FSB409	LS1317	AUDI
K942	GS8596	FSB520	LS1651	SUZUKI
K459				NISSAN
698	GS8682			KIA
	GS8439	FSB612	LS1326	MAZDA
K386	GS8694		LS1876	MAZDA
K6707				MITSUBISHI
	GS8150	FSB83	LS1305	VOLKSWAGEN
	GS8204	FSB86	LS1375	
	GS8635	FSB567	LS1716	CITROEN

	GS8272	FSB575/FSB268	LS1813	424155	PEUGEOT
K015					TOYOTA
K031					DAIHATSU
K021					DAIHATSU
K040					DAIHATSU
	GS8271	FSB232			CITROEN-PEUGEOT
K747	GS8584	FSB339	LS1604		SUBARU
K2308					TOYOTA
K017					
K388	GS8663	FSB611			MAZDA
K340					MAZDA
	GS6152	FSB152	LS1241		HYUNDAI
K2302					TOYOTA
	GS8539 / GS8629	FSB542	LS1631		FORD (EUROPE)
	GS8549	FSB331			SUZUKI
	GS6211	FSB199	LS1297		OPEL
	GS8443	FSB684			FORD-MAZDA
	GS8690	FSB590R			FORD
K189	GS8590	FSB683	LS1709		NISSAN
K3387					MAZDA
					DODGE
					LAND ROVER
					CHEVROLET
					MITSUBISHI
					CHEVROLET
					GMC
	GS8607	FSB552			FORD (EUROPE)
	GS8534 / G8605	FSB519	LS1691		FORD
	GS8269	FSB263	LS1378		FIAT
K913	GS8260	FSB260	LS1576		MAZDA
	GS8155				FORD (EUROPE)
	GS8658	FSB586			HYUNDAI
					MITSUBISHI
K3406					MAZDA
					LINCOLN-MERCURY
	GS8637	FSB545	LS1729		SATURN
					CHEVROLET
					FORD
					KIA
K959					SUZUKI
					GMC
					KIA
		FSB679			CHEVROLET
K395	GS8611	FSB543			MAZDA- FORD(EUROPE)
					CADILLAC-BUICK
					FORD
K2395	GS7811				TOYOTA
K3367					MAZDA-MITSUBISHI

K3366					MAZDA-MITSUBISHI
					ISUZU COMMERTIAL
K3240C/K2378					TOYOTA
					HINO-INTERNATIONAL
K1247	GS8487				NISSAN
	GS8473	FSB655			FIAT
	GS8707				HYUNDAI
					NISSAN
	GS8322				PEUGEOT
	GS8211 / GS8462	FSB243		4241K5	RENAULT
K026					DAIHATSU
	GS8696				HYUNDAI
	GS8642	FSB576			SATURN-PONTIAC
					OLDSMOBIL-PONTIAC
K2333	GS8672	FSB564			TOYOTA
					KIA-HYUNDAI
					DODGE
K4404					ISUZU
	GS8616	FSB544			RENAULT
K729					SUBARU
K730					SUBARU
K640					mitsubishi
K934	GS8301	FSB316			SUZUKI
K121					NISSAN
K122	GS8032	FSB31			NISSAN
					NISSAN
K2335A					TOYOTA
K959A					SUZUKI
	GS8567	FSB529	LS1700		DODGE
K2335(S4465A)					TOYOTA
					LEXUS-TOYOTA
					CHEVERLOT
					FORD-MERCURY
					JEEP
					TOYOTA-SCION
					JEEP
					KIA
K146A					NISSAN
K519					HONDA
					CHRYSLER
K2339					TOYOTA
	GS8454	FSB635			FORD
					HONDA
	GS8537	FSB421	LS1683		MERCURY
					CHRYSLER-DODGE
K3369					MAZDA-KIA
K9919					SUZUKI-MAZDA
					DODGE-PLYMOTH
					FORD-MERCURY

					CHRYSLER-DODGE
					PONTIAC- CHEVROLET
					TOYOTA
					HYUNDAI-KIA